

Carter Monohull



Listing Details

Subtype	Monohull
Make	Carter
Model	
Status	Available for sale
Year	1976
Stock/Ref #	TY3834
Engine Make	Perkins 4108
Engine Year	1976
Total Eng Power	40 HP
No. of engines	1
Engine Type	Diesel
Fuel Capacity	100 Ltr
Hull Construction	Tripple skin Kauri glassed
Displacement	8000 kgs
Hull Material	Timber
Deck/Cabin Construction	Teak deck, ply glass cabin
Designer	Dick Carter
Builder	Orams Whangarei
Hull Length	12.20 m
Draft	1.80 m
Covers / Bimini / Dodger	Yes
Water Tank Material	Stainless steel
Other Batteries	1
Electronics / Navs	GPS
CD Player	CD, radio
Davits	Yes
Depth Sounder	Yes
Compass	Yes
Capstan	Yes
Auto Pilot	Yes
VHF	Yes
Clock	Yes
Barometer	Yes
SSB	Yes
GPS	Yes
Log	Yes
Wind Inst	Yes
Fire Ext	Yes
Flares	Yes
Gas Detector	Yes

## Description

12.2m Carter 40 yacht. Launched in 1976 she has a triple skin Kauri glassed hull, teak decks and ply glass cabin. The sail wardrobe consists of Main, Genoa, 2 x Spinnakers, Light Wind Head Sail and a Staysail. She sleeps 5 across 2 cabins and would make a good family yacht. Are you the person to give this lady some loving to bring her back to her former glory?

**Accommodation** 5 berths across 2 cabins

**Eng Cyls** 4

**Fuel Tank Material** Stainless Steel

**Drive Propulsion** Kiwi folding

**Max Speed** est. 11 knots

**Anchor** Danforth

**Chain** est. 45m (new 2018)

**Headroom in Saloon** 6ft

**Water Pressure** Yes

**Shower** 1

**Toilet** 1

**Holding Tank** Yes

**Stove/Oven** Yes

**Fridge** 1

**Freezer** 1

**Water Tank Capacity** est. 200Ltrs

**Hot Water** Yes

**Bilge Pump** Manual and electric

**Start Batteries** 1

**Standing Rigging Details** Self furling Main, Genoa

**Steering** Auto pilot

**Sails Details** Main, Genoa, 2 x Spinnaker, Light Wind Head Sail, Staysail

**Dinghy** Yes

**Outboard** Yes

**Fenders** Yes

**Windlass** Yes

**Shore Power** Yes

**B'ding Ladder** Yes

## Tauranga Boat Sales

Ph: 07 5750512

The Tauranga Bridge

Marina

Causeway, Tauranga NZ 3110

**Disclaimer:** This information is a guide only. It is the customers responsibility to verify the accuracy of this information.